


[붙임 1. 측정결과]

	시료번호	측정 지점	측정 장비 (종류/수량)	유량 (ℓ/분)	측정 일시	측정 결과 (f/cc)	검출석면의 종류
측정 결과	#A01	부지경계선 1	YSP1045S/1	11.47	2020.04.02	0.001	백석면
	#A02	부지경계선 2	YSP1045S/1	11.04	2020.04.02	0.001	백석면
	#A03	부지경계선 3	YSP1045S/1	11.50	2020.04.02	0.001	백석면
	#A04	부지경계선 4	YSP1045S/1	11.46	2020.04.02	0.001	백석면
	#A05	작업장주변(실외) 1	YSP1045S/1	11.25	2020.04.02	0.001	백석면
	#A06	위성설비입구 1	YSP1045S/1	11.65	2020.04.02	0.001	백석면
	#A07	폐기물보관지점 1	YSP1045S/1	11.51	2020.04.02	0.001	백석면
	#A08	폐기물보관지점 2	YSP1045S/1	11.21	2020.04.02	0.001	백석면
	#A09	폐기물보관지점 3	YSP1045S/1	11.72	2020.04.02	0.001	백석면
	#A10	폐기물보관지점 4	YSP1045S/1	11.30	2020.04.02	0.001	백석면

[붙임 2. 측정지점]



측정 지점	비산측정 시작 사진	비산측정 종료 사진	비고
#A01 부지경계선 1			-
	측정 시작 시간 : 10:15	측정 종료 시간 : 14:15	
#A02 부지경계선 2			-
	측정 시작 시간 : 10:16	측정 종료 시간 : 14:16	
#A03 부지경계선 3			-
	측정 시작 시간 : 10:18	측정 종료 시간 : 14:18	
#A04 부지경계선 4			-
	측정 시작 시간 : 10:19	측정 종료 시간 : 14:19	
#A05 작업장주변(실외) 1			-
	측정 시작 시간 : 10:23	측정 종료 시간 : 12:23	

측정 지점	비산측정 시작 사진	비산측정 종료 사진	비고
#A06 위생설비입구 1			-
	측정 시작 시간 : 10:34	측정 종료 시간 : 11:14	
#A07 폐기물보관지점 1			-
	측정 시작 시간 : 13:38	측정 종료 시간 : 14:18	
#A08 폐기물보관지점 2			-
	측정 시작 시간 : 13:40	측정 종료 시간 : 14:20	
#A09 폐기물보관지점 3			-
	측정 시작 시간 : 14:21	측정 종료 시간 : 15:01	
#A10 폐기물보관지점 4			-
	측정 시작 시간 : 14:22	측정 종료 시간 : 15:02	